

ACB - Car Paint Mixing Direction

2K Clearcoat Mixing

2K Clearcoat C6000	+	Hardener H680	+	Thinner TX-2
2		1		0.3 - 0.5

2K Color Mixing

2K Color BK-101	+	Hardener H680	+	Thinner TX-2
2		1		0.2 - 0.4

1K Color Mixing

1K Color AK-101	+	Thinner TX-2
2		0.9 - 1

1K Primer Surfacer Mixing

1K Primer Surfacer P200	+	Thinner TX-2
1		1 - 1.2

2K Primer Surfacer Mixing

2K Primer Surfacer P200	+	Hardener H200	+	Thinner TX-2
4		1		1.2 - 2

1K Plastic Primer Mixing

1K Plastic Primer P300
No need add Additives

2K Epoxy Primer Mixing

2K Primer Surfacer P400	+	Hardener H400	+	Thinner TX-10
4		1		1 - 1.4

Polyester Putty Mixing

Polyester Putty F200	+	Hardener
1		0.02 - 0.03

NC Putty Mixing

NC Putty F100
No need add Additives